


Wobble Tuning the Probe (Wobbling)

Adjust Probe Tune and Match



Spectrometer
Frequency

Resonant
Frequency
of Probe
Coil

Do Not
Exit Loc
Window

The user can
adjust probe
tune and
match. Exit
window
(Alt+F4) or
click...

Bad Shims?

> rsh